

## IEEE 802.17 Maintenance Request 0118

MR number 0118 Classification Technical Date received 9/15/2006 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 357 Subclause \_\_\_\_\_ Figure \_\_\_\_\_ Table 11.20

Surname Juźwiak Given Name Piotr

**Perceived Problem** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Inconsistent notation "frame.checksumValid" in Table 11.20 rows 6 and 9 although subclause 11.3.2.5 calls this field of TC frame "cv" and Table 11.19 contains notation frame.cv (row 6).

**Proposed Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Change all occurrence of „frame.checksumValid" to "frame.cv".

**Rationale For Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Notation will be more clear.

**Remedy's Effect On Existing Equipment** [ If more space is needed, provide an additional file, preferably as plain text. ]

No impact.

**When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.**