

IEEE 802.17 Maintenance Request 0123

MR number 0123 Classification Technical Date received 9/15/2006 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 78 Subclause 7.2.1 Figure _____ Table _____

Surname Juźwiak Given Name Piotr

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

There is no definition of queue Q_TX_ROUTE in 7.2.1. Queue is used in TransmitCount and TransmitRoute state machines.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Add some definition of Q_TX_ROUTE.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

No impact.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.