

IEEE 802.17 Maintenance Request 0128

MR number 0128 Classification Technical Date received 9/15/2006 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 330 Subclause _____ Figure _____ Table 11.13

Surname Juźwiak Given Name Piotr

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

There is a wrong notation of condition „currentTime-wtr[ri].time >= wtr.timeout[ri]” in Row 11 Table 11.13.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Changing “wtr.timeout[ri]” to “wtr[ri].timeout”.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Timeout variable in wtr struct defined in 11.2.3 is not an array.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.