
AUI and PPI Interfaces



- XSR/Direct drive generally require optics engine to be bumped and the interface is an engineered analog drive not an AUI interface
 - With in the scope of 802.3df we have potentially up to 4 AUI classes and as few as 2 classes!

