

Dallas CX-4 Meeting March 11,3002

Request for change John DeAndrea

3/11/2003



Table 54-6 Driver Requirements

Present Specification:

• Common Mode Signal: Maximum + 1.9 V

Minimum - 0.4 V

Proposed Changes to Specification:

• Common Mode Signal: Maximum +2.0 V

Minimum - 2.0 V

Reason: Allow alternate implementations for Transmitter configurations

Risks: None

3/11/2003



Table 54-6 Driver Requirements

Discussion

- Why specify Vcm?
- For ESD/protection, transmitter may contain transformer or DC blocks
- Vcm would then be 0 volts
- This would suggest balance of specification for +/- levels

3/11/2003