

IEEE P802.3BP, DRAFT D1.4 STATUS

MAREK HAJDUCZENIA
P802.3BP CHIEF EDITOR

Draft D1.4 status



- D1.4 Task Force review closed on the 8th of May 2015 (EOA)
- 244 comments received within the allocated time, no post deadline comments received so far
 - 70 TR, ER, GR comments
 - 125 technical comments (T + TR)
 - 119 editorial comments (E + ER).
- Majority of comments focused on Clauses 97 and 98
- There are comments addressing missing items in Clause 30, and fixing register definitions in Clause 45
- Some comments are still mislabeled
 - Editorial comments calling for technical changes ...
 - Technical comments calling for missing commas ...

Major Comments (1)



Clause 30:

#332: missing material

Clause 45 registers:

- #536 (alignment with 802.3bw needed) and associated comments: #555,
 #401, #496, #492, #450, #449, #451, #452, #497, #493, #351, #357, #494,
 #495,
- #544: "atomically", "automatically", or something else?
- #356, #498, #358, #500, #360 & #505, #361 & #556, #363
- #364: next page registers

• Clause 78:

- #444: Min and Max for Tr, Tq, and Ts parameters
- #557, #343: case 1 & case 2 parameters

Major Comments (2)

Clause 97:

- Changes to Figure 97-22: #342, #542, #568, #543, #569
- Changes to Figure 97-23: #570, #540,
- Changes to Figure 97-2: #434
- Changes to Figure 97-3: #437
- Changes to Figure 97-4: #433
- Changes to Figure 97-9: #558
- Changes to Figure 97-15: #415, #571
- Changes to Figure 97-12: #344
- Changes to Figure 97-14: #345
- Cabling naming: #513
- MB/d versus Megabaud: #368
- Training sequence: #538
- "code-group" versus "symbol": #402
- PMA RESET.indication: #432
- rem rcvr status: #541
- OAM effect on LPI: #410, #371
- Placement of within a data frame: #348, #436
- RFER CNT LIMIT: #372, #412
- Register numbering alignment: #374, #373, #375, #563, #549,
- 256 repetitions: #564
- Changes in DataSwPFC24: #420, #424, #349
- Missing watchdog definition: #376
- Missing PMD requirements: #336, #523, #524, #337, #338, #404
- "dummy zero": #539, #574



Major Comments (3)



- Clause 98:
 - Changes to Figure 98-4: #384
 - Changes to T1/T5/T6 timers: #575, #385, #386
 - Missing electrical spec: #399



QUESTIONS