

# 802.3bq Editor's Report

George Zimmerman  
CME Consulting  
Chief Editor


# Status – updated as of 4/13/16

- Draft 3.2 Sponsor Ballot Recirculation
  - Opened 21-Mar-2016 closed 5-Apr-2016
    - 8 comments from 2 ballots received, no new negatives

	D3p0	D3p0%	D3p1	D3p1%	D3p2	D3p2%	Req'd
<b>Voters</b>	<b>128</b>		<b>128</b>		<b>128</b>		
<b>Return</b>	<b>102</b>	<b>79.7%</b>	<b>109</b>	<b>85.2%</b>	<b>111</b>	<b>86.7%</b>	<b>&gt;50%</b>
<b>Approve</b>	<b>89</b>	<b>90.8%</b>	<b>101</b>	<b>95.3%</b>	<b>104</b>	<b>97.2%</b>	<b>&gt;75%</b>
<b>Disapprove w/comment</b>	<b>9</b>	<b>9.2%</b>	<b>5</b>	<b>4.7%</b>	<b>3</b>	<b>2.8%</b>	<b>&lt;25%</b>
<b>Disapprove w/o comment</b>	<b>1</b>	<b>1.0%</b>	<b>0</b>	<b>0.0%</b>	<b>0</b>	<b>0.0%</b>	
<b>Abstain</b>	<b>3</b>	<b>2.9%</b>	<b>3</b>	<b>2.8%</b>	<b>4</b>	<b>3.6%</b>	<b>&lt;30%</b>
<b>Comments</b>	<b>182</b>		<b>15</b>		<b>8</b>		
<b>Late Comments</b>	<b>6</b>				<b>2</b>		

- Results above for D3p0 and D3p1 are as of ballot close, not including vote flips during resolution
- 2 late comments are expected to be received, based on email prior to this meeting

# Distribution of Comments



Distribution: d3p0: 109 E, 3 ER, 37 T, 27 TR, 2 G, 4 GR  
 d3p1: 9 E, 0 ER, 5 T, 0 TR, 0 G, 1 GR  
 d3p2: 4 E, 4 T

# Editorial Team

---

- George Zimmerman, Chief Editor
- Chris Diminico, Editor
- Valerie Maguire, Editor
- Jim Graba, Editor
- Curtis Donahue, Editor

# Editorial Responsibilities

Clause	Amendments	Owner
<b>1</b>	New normative refs, defns, abbreviations	Val
<b>28</b>	Auto-Negotiation support for new PHY	Val
	Annex 28b, 28C, 28D	Val
<b>30</b>	Add new management objects/attributes	Val
<b>45</b>	Add new registers/bits	Val, George
<b>78</b>	Add new Energy Efficient PHYs	Jim
<b>80</b>	40 Gb/s overview	Val, George
<b>81</b>	XLGMII	Val, George
<b>82</b>	EEE signaling and state machines	George
<b>105</b>	25 Gb/s Ethernet Overview	George
<b>113</b>	40GBASE-T 113.1-.6, 9, Annex 113A	George
<b>113.7</b>	113.7 channel	Chris
<b>113.8</b>	113.8 MDI	Chris

# Summary by Topic

---

- 8 Total Comments
  - 4 EZ (no motion expected)
  - 4 Related to “Invalid Blocks” subclause

# Big Ticket Items

---

- None: No new required comments
  - Previous unsatisfied comments:  
[http://www.ieee802.org/3/bq/comments/8023bq\\_unsatisfied\\_post\\_d3p1.pdf](http://www.ieee802.org/3/bq/comments/8023bq_unsatisfied_post_d3p1.pdf)
    - Use of “Either/or” – no remedy offered
    - Add Class FA for 25GBASE-T Cabling Types – no consensus for change
    - Request to make the MDI optional; no normative MDI connector type – no consensus for change
- SCOPE: Only unchanged text or unsatisfied comments are in scope;
  - HOWEVER, we are coming to our last chance to fix errors in the draft
  - Consider whether an error would cause misunderstanding requiring a corrigendum

# Late Comments

- 2 late comments received, related to editorial errors:

Category	Page	Sub-clause	Line	Comment	Proposed Change	Must Be Satisfied
Technical	125	113.3.6.2.4	52	<p>“b) a block type field 0x4B, a valid O code, and zeros, as shown in Figure 82-4;”            Figure 82-4 is the wrong reference. Rather than point to Figure 113-10 ( the correct figure), I think this reference is unnecessary and can be deleted.            The same reference error appears on page 126 line 39.</p>	<p>Page 125 line 52 delete “, as shown in Figure 82-4”            page 126 line 39 delete “as shown in Figure 82-4”</p>	No
Editorial	103	113.3.2.2.6	28	<p>Table 113-1 starts on page 102 and continues on page 103 at line 28, however Figure 113–10 appears between the split.            This was introduced in draft 3.1.</p>	<p>Beat Framemaker into submission and move Figure 113–10 out of the split table.</p>	No



# EZ Bucket

---

- No EZ bucket motion is expected this time