

+-----+
| 8802-3/802.3 REVISION REQUEST 1217 |
+-----+

DATE: 23 of February, 2010
NAME: Marek Hajduczenia
COMPANY/AFFILIATION: ZTE Corporation
E-MAIL: marek.hajduczenia@zte.com.cn

REQUESTED REVISION:
STANDARD: IEEE 802.3av-2009
CLAUSE NUMBER: 76.2.2.3
CLAUSE TITLE: Dual-rate mode

PROPOSED REVISION TEXT:
In IEEE 802.3av-2009, Figure 76-4 - 'PCS and Reconciliation Sublayer for dual rate mode at OLT' contains four numeric errors, as marked in red boxes in file 'Figure 76-4 in 802.3av-2009.pdf'.
Box 1 (top row, leftmost): '10 Gb/s' should read '1 Gb/s'
Box 2 (top row, rightmost): '10 Gb/s' should read '1 Gb/s'
Box 3 (bottom row, leftmost): '10 Gb/s' should read '1 Gb/s'
Box 4 (top row, rightmost): '10/10 Gb/s' should read '10/1 Gb/s'
Correct figure is included in the file 'Figure 76-4 in 802.3av D2.0.pdf'.

RATIONALE FOR REVISION:
This figure is technically incorrect and needs to be updated to a correct version prior to release of IEEE Std 802.3-2011.

IMPACT ON EXISTING NETWORKS:
None.

+-----+
| Please attach supporting material, if any |
| Submit to:- David Law, Chair IEEE 802.3 |
| and copy:- Wael William Diab, Vice-Chair IEEE 802.3 |
| At:- E-Mail: stds-802-3-maint-req@ieee.org |
| +----- For official 802.3 use -----+ |
| REV REQ NUMBER: 1217 |
| DATE RECEIVED: 23rd Feb, 2010 |
| EDITORIAL/TECHNICAL |
| ACCEPTED/DENIED |
| BALLOT REQ'D YES/NO |
| COMMENTS: XX-Xxx-XX Ver: D1.0 Status: R |
+-----+

+-----+
| For information about this Revision Request see - |
| http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1217 |
+-----+




Figure 76-4—PCS and Reconciliation Sublayer for dual rate mode at OLT




Figure 76-4—PCS and Reconciliation Sublayer for dual rate mode at OLT