

+-----+
| 8802-3/802.3 REVISION REQUEST 1261 |
+-----+

DATE: 13th June, 2014
NAME: Arthur Marris
COMPANY/AFFILIATION: Cadence Design Systems
E-MAIL: arthurm@cadence.com

REQUESTED REVISION:
STANDARD: IEEE Std 802.3bj-2014
CLAUSE NUMBER: 82
CLAUSE TITLE: Figure 82-17 LPI Receive state diagram

PROPOSED REVISION TEXT:

Delete vestigial entry B into state RX_LINK_FAIL.

RATIONALE FOR REVISION:

The B entry condition should have been removed when the RX_FW state was removed from this diagram but it was left in by accident.

IMPACT ON EXISTING NETWORKS:

None.

+-----+
| Please attach supporting material, if any
| Submit to:- David Law, Chair IEEE 802.3
| and copy:- Adam Healey, Vice-Chair IEEE 802.3
|
| At:- E-Mail: stds-802-3-maint-req@ieee.org
|
| +----- For official 802.3 use -----+
| REV REQ NUMBER: 1261
| DATE RECEIVED: 13th June, 2014
| EDITORIAL/TECHNICAL
| ACCEPTED/DENIED
| BALLOT REQ'D YES/NO
| COMMENTS: XX-Xxx-XX Ver: D1.0 Status: R
|
+-----+
| For information about this Revision Request see -
| http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1261
+-----+