```
REVISION REQUEST
2
 3
 4
    DATE: 11/6/2018
5
    NAME: Duane Remein
6
    COMPANY/AFFILIATION: Huawei Technologies, Inc.
7
   E-MAIL: duane.remein@huawei.com
8
   REQUESTED REVISION:
9
10
     STANDARD: IEEE Std 802.3-2018
11
     CLAUSE NUMBER: 45
12
     CLAUSE TITLE: Management Data Input/Output (MDIO) Interface
13
   PROPOSED REVISION TEXT:
14
    Change the Description for bit 3.18.13 from:
15
    "1 = PCS is able to support 2.5GBASE-T PCS type
16
    0 = PCS is not able to support 2.5GBASE-T PCS type" to:
17
    "1 = PCS is able to support 5GBASE-T PCS type
18
    0 = PCS is not able to support 5GBASE-T PCS type"
19
20
   Change the Description for bit 3.18.12 from:
21
    "1 = PCS is able to support 5GBASE-T PCS type
22
   0 = PCS is not able to support 5GBASE-T PCS type" to:
23
    "1 = PCS is able to support 2.5GBASE-T PCS type
24
    0 = PCS is not able to support 2.5GBASE-T PCS type"
25
26
27
   RATIONALE FOR REVISION:
28
    Table 45-181-PCS status 2 register bit Descriptions are incorrect.
29
    The Description for Bits 3.8.12 and 3.8.12 are swapped.
30
    See 802.3-2018 Section 4 pg 240 subclause 45.2.3.7
31
32
    IMPACT ON EXISTING NETWORKS:
33
    Potential interoperability and incompatible bit usage in
34
   PCS status 2 register (Register 3.8)
35
36
    +-----
37
    |Please attach supporting material, if any
    |Submit to:- David Law, Chair IEEE 802.3
38
    |and copy:- Adam Healey, Vice-Chair IEEE 802.3
39
40
41
    |At:- E-Mail: stds-802-3-maint-req@ieee.org
42
    43
                +----- For official use -----+
                | REV REQ NUMBER: 1325
44
                | DATE RECEIVED: 6 November 2018
45
                | EDITORIAL/TECHNICAL
46
47
                | ACCEPTED/DENIED
48
                | BALLOT REO'D YES/NO
   49
               | COMMENTS:
50
    +-----
51
   | For information about this Revision Request see -
   |http://www.ieee802.org/3/maint/requests/revision history.html#REQ1325 |
52
53
```