

```

1  +-----+
2  |                                     |
3  +-----+
4  DATE: 07/13/2020
5  NAME: DAVID MALICOAT
6  COMPANY/AFFILIATION:
7  MALICOAT NETWORKING SOLUTIONS / SENKO ADVANCED COMPONENTS
8  E-MAIL: david.malicoat@gmail.com
9
10 REQUESTED REVISION:
11   STANDARD: 802.3-2018
12   CLAUSE NUMBER: 86.10.3.2
13   CLAUSE TITLE: Optical Lane Assignments for 100GBASE-SR10
14 PROPOSED REVISION TEXT:
15
16 Figure 86-7 occurs in the document after figure 86-8
17
18
19
20 RATIONALE FOR REVISION:
21
22
23 When reading the document it appears that figure 86-6 is missing
24 because figures 86-6 and 86-8 are on the same page. Figure 86-7
25 appears on the following page.
26
27
28
29 IMPACT ON EXISTING NETWORKS:
30
31 There should be no impact to existing networks.
32
33
34 +-----+
35 |Please attach supporting material, if any
36 |Submit to:-   David Law, Chair IEEE 802.3
37 |and copy:-   Adam Healey, Vice-Chair IEEE 802.3
38 |
39 |At:-         E-Mail: stds-802-3-maint-req@ieee.org
40 |
41 |             +----- For official use -----+
42 |             | REV REQ NUMBER: 1365                |
43 |             | DATE RECEIVED: 13 July 2020        |
44 |             | EDITORIAL/TECHNICAL                |
45 |             | ACCEPTED/DENIED                    |
46 |             | BALLOT REQ'D      YES/NO           |
47 |             | COMMENTS:                          |
48 +-----+
49 | For information about this Revision Request see -
50 |http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1365 |
51 +-----+

```