

**Interpretation Number:** 4-03/03  
**Topic:** Test Fixtures  
**Relevant Clause:** 40.6.1.1.3  
**Classification:** Not a request for Interpretation

### **Interpretation Request**

Refer to IEEE802.3 2000 standard clause 40.6.1.1.3, is the test fixture setup shown in Figure 40.22 correct?

I have setup my test fixture (the 50ohms and 100ohms termination for each pair) and the testing equipment exactly the same shown in this figure but the result obtained is incorrect. Please advise.

---

### **Interpretation for IEEE std 802.3-2002**

This request is being returned to you because it does not constitute a request for interpretation but rather a request for a consultation advice. Generally, an interpretation request is submitted when the wording of a specific Clause or portion of the standard is ambiguous or incomplete. The request should state the two or more possible interpretations or the lack of completeness of the text.

Filename: interp-4-0303.doc  
Directory: D:\My Documents\IEEE\802.3\_Interp\interp\_03\_03\open  
Template: C:\Program Files\Microsoft Office\Templates\Normal.dot  
Title: Interpretation Number: x  
Subject:  
Author: David Law  
Keywords:  
Comments:  
Creation Date: 24/05/02 18:45  
Change Number: 6  
Last Saved On: 13/03/03 13:01  
Last Saved By: David Law  
Total Editing Time: 159 Minutes  
Last Printed On: 19/03/03 20:03  
As of Last Complete Printing  
Number of Pages: 1  
Number of Words: 129 (approx.)  
Number of Characters: 737 (approx.)